


Building Dashboard

City Hall			14 Court Square					
Building Data								
Structural Details		HVAC		Appliances	Type/age			
1848; occupied as City Hall since 1964	Heating System	VRF heat pumps Gas-fired Steam as backup	EXCELLENT GOOD	Interior Lighting	all upgraded to LEDs 2018			
16,430	Heat Distribution	units installed in	EXCELLENT	Exterior Lighting	LEDs in Parking Lot/Building exterior			
Brick Envelope, Vinyl covered wood frame roof, Vinyl Replaced 2012	Air Conditioning		EXCELLENT	Refrigerator	2016 - New Energy Star			
Both Gable and Flat Roof Replaced in 2018	Ventilation	Passive	N/A	Vending Machine	None			
Double Pane Installed - 2012	Hot Water Heater	2016 - Heat Pump Water Heater	EXCELLENT	Water Fountains	New in 2017			
Walls - None (solid brick) Attic - 12" Loose Fiberglass	Emergency Generator	150 kW Diesel	EXCELLENT					
	Structural Details 1848; occupied as City Hall since 1964 16,430 Brick Envelope, Vinyl covered wood frame roof, Vinyl Replaced 2012 Both Gable and Flat Roof Replaced in 2018 Double Pane Installed - 2012 Walls - None (solid brick)	Buildin Structural Details HVA 1848; occupied as City Hall since 1964 16,430 Heat Distribution Brick Envelope, Vinyl covered wood frame roof, Vinyl Replaced 2012 Both Gable and Flat Roof Replaced in 2018 Double Pane Installed - 2012 Walls - None (solid brick)	Structural Details 1848; occupied as City Hall since 1964 16,430 Heat Distribution Brick Envelope, Vinyl covered wood frame roof, Vinyl Replaced 2012 Both Gable and Flat Roof Replaced in 2018 Double Pane Installed - 2012 Walls - None (solid brick) Building Data Heat Distribution Heating System System Cas-fired Steam as backup 2018 - Heat pump units installed in offices and hallways Ventilation Passive 2016 - Heat Pump Water Heater	Building Data	Structural Details			

Building Summary 2008 - Boiler replaced. 2012 - Windows and siding replaced. 2013 - Annex Removed. 2014 - Boiler burner changed from oil to gas. 2018 - Heating and cooling systems upgraded to VRF Heat Pumps. Challenges: Solid masonry construction does not allow for wall insulation





Completed Work							
Fiscal Year	Project	Project Cost	Grants/Rebates	Life Expectancy	Warranty		
2012	Window Replacement (ARRA Funding)	N/A	N/A	10-20 years	expired		
2017	Heat Pump Hot Water Heater	\$1,037	\$173	10-12 years	10 year		
2017	Water fountain Replacement	N/A	none	N/A	TBD		
2017	Diesel Emergency Generator Installation (replacing smaller generator installed in 2016)	\$60,000	none	10,000 to 30,000 hours	TBD		
2018	Roof replacement - shingles and membrane	\$85,000	none	30-40 years	30 yrs - membrane 40 yrs - architectural shingles		
2019	Air-Source Heat Pumps Installation (Green Communities Grant)	\$138,525	\$96,845	20+ years	10 years - compressor & parts		
2019	LED lighting upgrade - on bill financed	\$11,479	\$5,222	20+ years	5 year lights/ 2 years labor		

Audits/Assessments				
Fiscal Year	Type Findings			
2009	Siemens Whole building assessment	Report available upon request		
2014	Clearesult	Suggestions for improving insulation, ventilation, and steam traps		
2016	CET Insulation Audit	Additional attic insulation unnecessary - would not be eligible for incentives		